

# Work Order ID 73928

Monday, September 19, 2011 12:49:11 PM



Ship Between  
Nov. 1-5th

Page 1

Item ID: D412-702-345

Accept



Setup Start



Revision ID:

Stop



Item Name: 4-Man Aft Facing Shoulder Harness, 3 point

Start Date: 9/19/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 9/21/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

*MF*

Date:

*11-09-19*

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

DSI9511

A

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP D412-702-345 CHG001

*S 11/09/10*

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

*11/9/10*

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

*S 11/09/10*

*XC*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 73928**

Monday, September 19, 2011 12:49:11 PM

Page 2

Item ID: D412-702-345

Accept

Setup Start

Revision ID:

Stop

Item Name: 4-Man Aft Facing Shoulder Harness, 3 point

Start Date: 9/19/2011 Start Qty: 1.00

Cust Item ID:

Required Date: 9/21/2011 Req'd Qty: 1.00

Customer:

Reference:

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start

QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

0.00



Packaging

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D412-702-345

Location: 52 A  
PPP Rev: \_\_\_\_\_C 11/9/2011 (1)

140

0.00



QC

QC21- Final Inspection - Work Order Release

Memo

0.00

Quality Control

11/9/2011MF  
11-09-20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Monday, September 19, 2011 12:49:08 PM

Page 1

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.

4. The fourth step is to implement the plan. This involves assigning tasks to team members, setting deadlines, and monitoring progress to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves comparing the actual outcomes with the original objectives and goals to determine the effectiveness of the project.



**Required Qty: 1.00**

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

\_\_\_\_\_



7

\_\_\_\_\_

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Picklist Print

Monday, September 19, 2011 12:49:08 PM

Page 2

Work Order ID: 73928

Parent Item: D412-702-345

Parent Item Name: 4-Man Aft Facing Shoulder Harness, 3 point

Start Date: 9/19/2011

Required Date: 9/21/2011

Start Qty: 1.00

Required Qty: 1.00

D3572-041

Manufactured No

110

Each

4.0000

2

2



Guide Assembly

Location

Loc Qty

Loc Code

ST260

4

68774

4

AN4-16A

Purchased

No

110

Each

134.0000

2

2



Bolt

Location

Loc Qty

Loc Code

ST358

134

117872

84

118838

50

AN4-25A

Purchased

No

110

Each

69.0000

4

4



BOLT

Location

Loc Qty

Loc Code

ST360

69

114330

19

116516

50

AN4-27A

Purchased

No

110

Each

31.0000

4

4



Bolt

Location

Loc Qty

Loc Code

ST360

31

116516

31

AN960JD416

NAS1149D0463J

Purchased

No

110

Each

0.0000

20

20



Washer



11118384

11/19/11

Monday, September 19, 2011 12:49:08 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



# Picklist Print

Monday, September 19, 2011 12:49:08 PM

Page 3

Work Order ID: 73928



Parent Item: D412-702-345



Parent Item Name: 4-Man Aft Facing Shoulder Harness, 3 point

Start Date: 9/19/2011

Required Date: 9/21/2011

Start Qty: 1.00

Required Qty: 1.00

MS21042L4

Purchased

No

110

Each

4,317.000

6

6



11/9/11 SP

Nut

Location

Loc Qty

Loc Code

ST300

4317

117441

51

117601

637

117885

629

118451

2000

118927

1000

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# REFERENCE ONLY

DART AEROSPACE LTD.

IIN-D412-702-2

Page 42 of 42

QTY -337	QTY -341	QTY -343	QTY -345	QTY -347	QTY -349	QTY -351	Part Number	Description
X							D214-702-337	Dart 5-Man 3 Point Aft Facing Shoulder Harness Kit, for 214 Aircraft
	X						D412-702-341	Dart 13-Man 3-Point Shoulder Harness Kit
		X					D412-702-343	Dart 5-Man 3-Point Forward Facing Shoulder Harness Kit
			X				D412-702-345	Dart 4-Man 3-Point Aft Facing Shoulder Harness Kit
				X			D412-702-347	Dart 4-Man 3-Point Side Facing Shoulder Harness Kit
					X		D412-702-349	Dart 1-Man 3-Point Forward Facing Shoulder Harness Kit
						X	D412-702-351	Dart 1-Man 3-Point Shoulder Harness Kit
	1	1		1	1		D412-702-059	GROMMET KIT
	2	1		1			D412-702-301	HARNESS ASSEMBLY
	2	1		1			D412-702-303	HARNESS ASSEMBLY
	1	1			1		D412-702-305	HARNESS ASSEMBLY
	1	1				1	D412-702-307	HARNESS ASSEMBLY
	1	1					D412-702-309	HARNESS ASSEMBLY
1	1		1				D412-702-311	HARNESS ASSEMBLY
1	1		1				D412-702-313	HARNESS ASSEMBLY
	1			1			D412-702-315	HARNESS ASSEMBLY
	1			1			D412-702-317	HARNESS ASSEMBLY
1							D412-702-319	HARNESS ASSEMBLY
1	1		1				D412-702-321	HARNESS ASSEMBLY
1	1		1				D412-702-323	HARNESS ASSEMBLY
	2	2				1	D3542-1	BRACKET
	7	3		4	1		D3571-1	GUIDE
	2	2				1	D3571-3	GUIDE
	2		2				D3572-041	GUIDE ASSEMBLY
	12	6		6	2		D3578-041	DOUBLER
	2	2				1	D3610-041	BRACKET
	2	2				1	D3618-1	CAP
				2			D3677-1	SPACER
	9	5		4	1	1	D3761-1-041	HOOK AND LOOP STRIP
1							D3920-041	SEATBELT GUIDE ASSEMBLY
2							D3920-5	SEATBELT GUIDE
	4	4				2	AN4-10A	BOLT
1	2		2				AN4-16A	BOLT
1							AN4-21A	BOLT
7	4		4				AN4-25A	BOLT
	4		4				AN4-27A	BOLT
	2	2				1	AN4-44A	BOLT
18	26	6	20			3	AN960JD416	WASHER (OR NAS1149D0463J)
	4	4				2	AN960JD416L	WASHER (OR NAS1149D0416J)
	24	12		12	4		CR3212-4-4	RIVET
9	12	6	6			3	MS21042L4	NUT (OR MS21042-4)
				6			MS21069L3	ANCHOR NUT
	2	2				1	MS24693S274	SCREW
				2			MS24694S282	SCREW
	3	3			1		MS24694S56	SCREW
	10	2		8			MS24694S58	SCREW
	1	1			1		MS24694S60	SCREW

• COPYRIGHT © 2010 BY DART AEROSPACE LTD •  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: A  
Date: 10.12.01